

Appendix A: Quality Site Audits

Indoor Sports Facility Quality Matrix

Name of facility	Cooden Beach Sports & Social Club
Address	TN39 3BD

QUALITY RATING

General Condition	Excellent	Good	Average	Poor	Very Poor	x
Need for capital investment	Minimal	Moderate	Significant			

Facility Quality						
Reception	Excellent	Good	Average	Poor	Very Poor	
Squash courts	Excellent	Good	Average	Poor	Very Poor	
Changing Room	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
	Excellent	Good	Average	Poor	Very Poor	
NB: MUST BE FILLED IN!! TOTAL NUMBER OF FACILITIES RATED						3

Disability Access	Full	Partial	No	
Served by Public Transport	Yes*	No		* a short walk away
Good Natural Presence	Excellent	Good	Average	Poor
Well Signposted	Good	Some	Poor	
Car Parking	Good	Some	Poor	
Development Potential	Lots	Some	No potential	

Key	Rating	0%
>80%	Excellent	
60% - 80%	Good	
40% - 59%	Average	
20%-39%	Poor	
<20%	Very Poor	

Notes on Facility Quality - Any proposed capital expenditure / what needs to be attended to e.g new roof, roof repairs, floor repairs, swimming plant upgrade required, changing rooms need refurbishing etc.